

## LIST OF FIGURES

Sl. No.	Figure No.	Description/Theme	Page No.
1	1.1	River Ganga and its Abandoned left-out Loops during the Last Retreat	5
2	1.2	Comprehensive Plan of Topographical Sheets (15'X15', 1:50,000 scales) of Malda District	9
3	1.3	Location of Study Area with Affected Blocks	11
4	2.1	Physiographic and Drainage personality of Malda District	21
5	2.2	Comprehensive Geological Framework of Bengal Basin with location of Bengal Gap	24
6	2.3	Tectonic Framework of Bengal with location of Transitional Geosyncline of Bengal Gap and Shields (Buried and Exposed)	28
7	2.4	Affected Mouzas in Bank Erosion of Manikchak Block (Census Years: 1981, 1991 & 2001)	48
8	2.5	Affected Mouzas in Bank Erosion of Kaliachak (I, II & III) Blocks (Census Years: 1981, 1991 & 2001)	49
9	2.6	Affected Mouza(s) in Bank Erosion of Englishbazar Block (Census Years: 1981, 1991 & 2001)	50
10	3.1	Location of Gour City at the east of River Ganga during the end of 17 <sup>th</sup> century	64
11	3.2	Location of Gour City at the west of River Ganga during middle of 15 <sup>th</sup> century	66
12	3.3	Ganga in a south-easterly direction during 19 <sup>th</sup> Century (Gour at the east)	67
13	3.4	Most straight course of Ganga during the beginning of the present Century between Rajmahal and Farakka	68
14	3.5	Stages of Development of Deltaic Plain of West Bengal and Bangladesh after Umitsu (1993)	70
15	3.6	Sub-Reach wise Location of Areas for the Assessment of River Energy	78
16	3.7	Diagrammatic presentation of Ground water table and channel water table at Panchanandapur	86
17	3.8	Gauge Level of River Ganga both upstream and downstream of Farakka Barrage	95
18	4.1	Sub Reach –wise identification of Geomorphic Parameters and Processes along the Left Bank of River Ganga.	107
19	4.2	Identification of Progressive Erosional Signatures on the Left Bank of River Ganga: Manikchak-Khaskol Reach	116
20	4.3	Identification of Progressive Erosional Signatures on the Left Bank of River Ganga: Khaskol-Panchanandapur Reach	117
21	4.4	Relationship study of Average bank Height (m) and	118-119

	(case 1,2,3)	other geo-morphic Parameters	
22	4.5	Relationship study of Average bank Height (m) and percentage Index of Erosion Hazards	120
23	4.6	Bank-side Rill and Gully Formations	131
24	4.7	Bank side cavity Forms	131
25	4.8	Toe Erosion	131
26	4.9	General Soil-scape of Lower Ganga Plains (Parts of Malda, West Bengal)	137
27	4.10	Bank Soil depth-wise distribution of share of sand, silt, and clay along the left bank of River Ganga	138
28	4.11	Depth-wise Distribution of Sand, Silt and Clay at Panchanandapur	141
29	4.12	Depth-wise Distribution of Sand, Silt and Clay at Domhat	141
30	4.13	Depth-wise Distribution of Sand, Silt and Clay at Manikchak	142
31	4.14 to 4.18	Bank Cross Section at sub-sites (01, 02, 03, 04, &05) of Panchanandapur	143-145
32	4.19	Location of Bank Cross Sections with Geographical Scenario of Panchanandapur Ghat Area	146
33	4.20	Reach -wise identification of occurrences of Geomorphic Parameters and Processes	149
34	4.21	Diagram on scour Depth Analysis (Panchanandapur and Manikchak)	154
35	4.22	Sediment Deposition within River Ganga (upstream of Farakka)	154
36	4.23	Model safety Factor Analysis	160
37	5.1	Spot-wise shifting distance over periods at Panchanandapur	165
38	5.2	Spot-wise shifting distance over periods at Sakullapur.	165
39	5.3	Spot-wise shifting distance over periods at Jotkasturi	166
40	5.4	Regression Analysis of year wise distance of bank line at Khaskol.	167
41	5.5	Distance from bank line over periods at Aswinitola site.	168
42	5.6	Five years of Moving Average Analysis of distance from bank line: Aswinitola Site.	169
43	5.7	Time series measurement of shifting from bank line: Manikchakghat Site.	170
44	5.8	Location of shifted Left Bank Line of the River Ganga over Time frame (Part I).	174
45	5.9	Location of shifted Left Bank Line of the River Ganga over Time frame (Part II).	175
46	5.10	Location of shifted Left Bank Line of the River Ganga over Time frame (Part III).	176
47	5.11	Distance of bank line of River Ganga over periods	177
48	5.12	Morphological Changes of Course from 1922 to2005 taking 88°00'E as Fixed Co-ordinate (1922-1938).	179
49	5.13	Morphological Changes of Course from 1922 to2005	180

		taking 88°00'E as Fixed Co-ordinate (1971-1981).	
50	5.14	Morphological Changes of Course from 1922 to 2005 taking 88°00'E as Fixed Co-ordinate (2002-2010)	181
51	5.15	Course shifting of River Ganga and its impact on affected mouzas (192-2011).	182
52	5.16	Shifting Pattern of River Ganga between Rajmahal and Farakka 1937-2011.	184
53	6.1	Location of Left Bank Line Spurs of River Ganga in Malda District.	188
54	6.2	Locations of Main Embankments along Left Bank Line of River Ganga in Malda District.	191
55	6.3 a	Embankments near Panchanandapur Area.	193
56	6.3 b	Embankments near Panchanandapur Area.	194
57	7.1	Figure 7.1 Contrast of Pre and Post Erosion Situation in Income: Panchanandapur.	205
58	7.2	Figure 7.2 Times of shifting of household: Panchanandapur.	205
59	7.3	Income (monthly) of Inhabitants at Manikchak: Before and after Erosion Condition (25 Households).	210
60	7.4	Loss of Bigha of Land at Manikchak: Before and After Erosion condition (25 Households)	210
61	7.5	Loss of Immovable Properties in Manikchak (25 Households).	211
62	7.6	Times of Shifting of settlement site (25 Households): Manikchak	211
63	7.7	Share of Homestead Land (Bigha): Panchanandapur (25 Households).	212
64	7.8	Production of Paddy Land before Erosion: Panchanandapur.	212
65	7.9	Share of Multi cropping Agricultural Land (Bigha): Panchanandapur (25 Households).	213
66	7.10	Land Occupancy: Before and After Erosion: Panchanandapur (25 Households).	213
67	8.1	Needful passage outlets to lessen water head pressure within the channel for Future River Training works	237
68	8.2	Location of Disposal Grounds I & II of Right Channel	240
69	8.3	Location of Disposal Grounds III & IV of Right Channel	240
70	8.4 a & b	Submersible suction Vanes and their possible location along bank line.	242

## List of Tables

Sl. No.	Table No.	Description/Theme	Page No.
1	1.1	Area of left Bank Erosion (Period 1922-23 to2003)	6
2	2.1	Geological time scale and formation of rocks (Bengal Basin Area)	29
3	2.2	Textural Classification of soil in Malda District	30
4	2.3	Soil orders and their characters	31
5	2.4	Major features of Diagnostic horizons	31
6	2.5	Alluvial Plain (Aa) Active Alluvial Plain (AaA)	33-34
7	2.6	Block wise Distribution of AaA soils (Diara soils)	34
8	2.7	Forest and Agriculture scenario in Malda and West Dinajpur Districts	43
9	2.8	Forest Classes in Malda and West Dinajpur	43
10	2.9	Block-wise areas under mango cultivation.	44
11	2.10	Decadal change of Population Growth in Malda	45
12	2.11	Report on erosion of affected blocks (1999-2001) in Malda District	46
13	2.12	Population Scenario of affected blocks in Malda	47
14	2.13	Mouza-wise distribution of Population and its Changing Pattern in Manikchak block during Census Years	51
15	2.14	Mouza-wise distribution of Population and its Changing Pattern in Kaliachak II block during Census Years	52-53
16	2.15	Mouza-wise distribution of Population and its Changing Pattern in Englishbazar block during Census Years	53
17	2.16	Mouza-wise distribution of Population and its Changing Pattern in Kaliachak III block during Census Years 1981-2001	54
18	2.17	Block-wise statement of affected Population	55
19	2.18	Block-wise statement on Impact of Erosion	56
20	2.19	Time series fluctuations in Land Valuation of selected sites	58
21	3.1	Physical properties of river bank and deposited bed materials	75
22	3.2	Bank Cross section-wise channel properties for water Head (m) calculation	76
23	3.3	Site-wise statements of channel Water Head (m)	76
24	3.4	Sub-Reach-wise Geographical Identity of Locations	79
25	3.5	Sub-Reach -wise statement of calculated Potential Energy	79
26	3.6	Velocities in $m s^{-1}$ near the eroding left bank between Khaskol & Panchanandapur	80
27	3.7	Velocity distribution at and far of bank	80
28	3.8	Bank Height character along the left bank ofGanga	82

29	3.9	Spot wise cavity lengths	85
30	3.10	Changing Population Scenario of Bhutni-Diara	88
31	3.11	Daily gauge level both up and down steam at Farakka of the river Ganga	94-95
32	3.12	Spot-wise width of main channel(LC) of River Ganga	96
33	3.13	Causative factors of Bank Erosion: A Stakeholder's perception	99
34	4.1	Calculation for bank height(Ht.) measurement Post monsoon, 2008	115
35	4.2	Comprehensive computations of model BEHI Analysis	118
36	4.3	Sub reach wise height-erosion hazard relationship (July 2005-2006)	119
37	4.4	Pre-Considered Parametric standards of Model Field Sheet	123
38	4.5	Sample profile characters of river Ganga in Malda district, West Bengal	133
39	4.6	Comprehensive soil properties (Mechanical Analysis) of 20 studies profiles	134
40	4.7	Average percentage share of sand, silt and clay	137
41	4.8	Percentage of organic carbon in the studied profiles (depth-wise)	139-140
42	4.9	Hydraulic Parameters of River Ganga at Panchanandapur area	143
43	4.10	Reach -wise identification of spots of Geomorphic parameters and processes along left bank of River Ganga	151
44	4.11	Comprehensive Assessment of Bank Erosion Hazard (2005-2006)	152
45	4.12	Relative Bank Material Loss Assessment (Monsoon, July 2008-09)	156
46	4.13	Comprehensive Bank Erosion Disaster Index (BEHI)	159
47	5.1	Mouza-wise statement of Erosion (Panchanandapur Site)	165
48	5.2	Comprehensive study on length of shift for three mouzas at Panchanandapur site	166
49	5.3	Statement of Erosion over Years (Khaskol Site)	167
50	5.4	Reduction of Bank Line distance: Manikchak Site	169
51	5.5	Year wise statement on left bank displacement of river Ganga (Manikchak to Farakka).	173
52	5.6	Comprehensive Framework of Leftward Shifting of the River Ganga.	178
53	6.1	Year wise statement of installation of Spurs.	187
54	6.2	Inter-spur Distance (m) along the Left Bank line of	195

		River Ganga.	
55	7.1	Change in Social space through Occupational Shift: Panchanandapur	200-201
56	7.2	Change in social space through Occupational Shift: Manikchak	201-202
57	7.3	Pre and Post income situation of bank erosion (25 unit family) Manikchakghat	203
58	7.4	Pre and Post income situation of bank erosion (25 unit family) Panchanandapur	204
59	7.5	Registering Social Disorderliness at selected spots (June 2008).	206
60	7.6	Newspaper Analysis on social Disorderliness.	206-208
61	7.7	Yearly loss of Land in Bank Erosion (1931-2000): Malda District.	209
62	7.8	Flood and Erosion Damages during 1998 and 1999.	214
63	7.9	Need based information at Panchanandapur on household Facility (80 families).	215
64	7.10	Demand of houses for rehabilitation in Bank Erosion.	215-216
65	7.11	Changes in Mango production in Malda.	220
66	7.12	Production and monitory profit of mango cultivation in Malda.	221
67	7.13	Allocation of money for Flood and Erosion: Share of State and Central Governments.	223
68	7.14	Accounting of six years of expenditure on Structural measures executed.	226-227
69	7.15	List of affected Mouzas with their area and population in Malda District.	228
70	7.16	Man-Land Ratio of 'indecision population' of Charlands.	232
71	8.1	Capacity -Cost features of Dredgers	237
72	8.2	Plan of deployment of Dredgers in a year	239
73	8.3	List of natural lakes in Malda in view of dam-linkage schemes	247

## List of Plates

Sl. No.	Plate No.	Description/Theme	Page No.
1	4.1	<i>The remnants of the 8<sup>th</sup> Embankment (Retired)</i>	104
2	4.2	<i>General bank Profiles in Diaras</i>	104
3	4.3	<i>Subsurface Flow Openings along the bank</i>	104
4	4.4	<i>Closer View of subsurface flow openings along the bank</i>	104
5	4.5	<i>Bank front remnants resting on the unconsolidated substrata</i>	105
6	4.6	<i>Semicircular rotational slip outs</i>	105
7	4.7	<i>Natural cracks introduced over banks</i>	105
8	4.8	<i>Subsurface fluting opening as narrow seepage gushers</i>	105
9	4.9	<i>Gravity collapse due to removal of subsurface support</i>	105
10	4.10	<i>Gravity collapse at the disposability</i>	105
11	4.11	<i>Cutting along the slip on side of bank near Domhat</i>	106
12	4.12	<i>Hydraulic shear stress action resulting into bank erosion</i>	106
13	4.13	<i>Areal Collapse of the bank front</i>	106
14	4.14	<i>Close view of Areal Collapse</i>	106
15	4.15	<i>Subsurface inflow passages</i>	106
16	4.16	<i>Gully Formations pouring down to the channel over silt bed.</i>	106
17	4.17	<i>Slip of bank material over bank foot</i>	109
18	4.18	<i>Creeping of loose materials</i>	109
19	4.19	<i>Depositional fashion of Band of sand and silt layers of the bank</i>	109
20	4.20	<i>Band of sands below overtopping silt layers of the bank</i>	109
21	4.21	<i>0.95m of thick silt band-pedon on 1.2m of high lustrous sand band</i>	109
22	4.22	<i>Subsidence of locally developed highly saturated clay part of bank</i>	109
23	4.23	<i>Slip of block of saturated soils of the bank</i>	111
24	4.24	<i>Block slip in motion(June 2008)</i>	111
25	4.25	<i>Collapse of almost sand dominated bank in impinge flow attacks</i>	111
26	4.26	<i>Weak bank due to seepage flow-outs through the horizontal subsurface conduit</i>	111
27	4.27	<i>Rotational cut-outs</i>	111
28	4.28	<i>Bank wasting in repeated parallel flow attacks</i>	111
29	4.29	<i>Phase-wise serial slump of bank soil upstream part of sakullapur</i>	112
30	4.30	<i>Inclined bank slope near Sakullapur (about 85° slope)</i>	112
31	4.31	<i>Field Data collection (Height measurement of bank)</i>	112
32	4.32	<i>Temporary resistance against bank failure offered by</i>	112

		<i>naturally developed reed lands</i>	
33	4.33	<i>Clay Dominated bank downstream of Panchanandapur</i>	113
34	4.34	<i>Friable sands sweeping away in late summer (June) in high velocity wind action associated with water hydraulic action</i>	113
35	4.35	<i>Corns under threats of erosion</i>	114
36	4.36	<i>Reeds under threats of erosion</i>	114
37	4.37	<i>Vertical cracks introduced on bank near Panchanandapur</i>	114
38	4.38	<i>Reeds and Mango Orchards under threats of erosion</i>	114
39	4.39 a & b	<i>Examining hardness of bank soil using geological Knife and Copper coin by the researcher</i>	114
40	4.40	<i>Rotational Slip.</i>	131
41	4.41	<i>Undermining of sand layer and slip down of overburden silt</i>	131
42	4.42	<i>Bank side block slumps</i>	131
43	6.1	<i>Inter spur spacing between Sakullapur-Panchanandapur.</i>	196
44	7.1	<i>Aesthetic preservation at the disposal of bank failure</i>	202
45	7.2	<i>Newly silting areas within channel and imprints of human occupancy for occupancy of Land(1,2,3,and 4 are the points of occupancy)</i>	218
46	8.1	<i>Deep root networking of vetiver Grass</i>	250
47	8.2	<i>Heavier weight of vetiver results into gravity attraction</i>	250
48	8.3	<i>Almost 1:1 Proportion Growth of stem and roots of vetiver signifying good soil holding capacity</i>	250
49	8.4	<i>Detachment of vetiver is really a harder task</i>	250
50	8.5	<i>Country boats as carriage of boulders from Rajmahal</i>	256
51	8.6	<i>Weir crates of boulders over unconsolidated silts of bank soils</i>	256
52	8.7	<i>Trilateral structure as protective measures against erosion</i>	257
53	8.8	<i>Location of Transverse Spurs with winged marginal guard walls</i>	258
54	8.9	<i>Thin polymer sheets to prohibit leaching through preparing embankment(Manikchak)</i>	259
55	8.10	<i>Unplanned boulder throwing to the Channel (Manikchak)</i>	259
56	8.11	<i>Carrying of boulders by labourers</i>	259
57	8.12	<i>Unplanned dumping of silt laden gunny bags affecting negatively to the bank soil compactness (Domhat)</i>	259
58	8.13	<i>Unplanned cutting of banks behind thick piles of marginal embankment pitching (Manikchak)</i>	259
59	8.14	<i>Wounded parts of silt laden gunny bags(Domhat)</i>	259
60	9.1	<i>Present Scenario at Panchanandapur</i>	272